




# Advanced Radon Services

## Sub Slab Depressurization – Inside Routing

### Notes:

1. Horizontal piping run in attic shown only for illustration. Stack could have penetrated straight upward through roof, if there were sufficient headroom to install fan at that location.
2. Electrical wiring to fan illustrated in later figure.



Routing through an attached garage is simple and cost-effective.